

Date	Time	instrument	analyte	reading	detection_flag	detection_limit	units	location_code	latitude	longitude	location_description	comments	additional_comments
04/14/2013	08:17	MultiRAE	VOC		<	0.1	ppm	50B	34.9640719	-92.4286207	East side of 50 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	very slight oil odor pipeline exposed vac truck in driveway ATRID1882
04/14/2013	08:19	MultiRAE	H2S		<	1	ppm	50B	34.9640719	-92.4286207	East side of 50 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	very slight oil odor pipeline exposed ATRID1882
04/14/2013	08:19	UltraRAE	Benzene		<	0.05	ppm	50B	34.9640719	-92.4286207	East side of 50 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	batch 303024 very slight oil odor pipeline exposed vac truck in driveway ATRID1882
04/14/2013	08:21	MultiRAE	VOC		<	0.1	ppm	50A	34.9639614	-92.4287148	East side of 50 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	slight oil odor pipeline exposed vac truck in driveway ATRID1882
04/14/2013	08:22	MultiRAE	H2S		<	1	ppm	50A	34.9639614	-92.4287148	East side of 50 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	slight oil odor vac truck in driveway pipeline exposed ATRID1882
04/14/2013	08:25	MultiRAE	VOC		<	0.1	ppm	44A	34.9637632	-92.4285727	West side of 44 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; Workers present; Slight Odor;	vac truck in driveway currently not running boom between yards slight oil odor ATRID1882
04/14/2013	08:26	MultiRAE	H2S		<	1	ppm	44A	34.9637632	-92.4285727	West side of 44 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; Workers present; Slight Odor;	slight oil odor vac truck in driveway currently not running boom in hard between homes ATRID1882
04/14/2013	08:28	UltraRAE	Benzene		<	0.05	ppm	44A	34.9637632	-92.4285727	West side of 44 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; boom present; Residence; Workers present; Slight Odor;	batch 303024 vac truck in driveway currently not running boom in hard between homes slight oil odor ATRID1882
04/14/2013	08:30	MultiRAE	VOC		<	0.1	ppm	44B	34.9638242	-92.4284833	West side of 44 Starlite Rd	No Visible Oil; Crude oil odor; Residence; Workers present; Slight Odor;	very slight oil odor workers cleaning dirt of bobcat ATRID1882
04/14/2013	08:32	MultiRAE	H2S		<	1	ppm	44B	34.9638242	-92.4284833	West side of 44 Starlite Rd	No Visible Oil; Crude oil odor; Residence; Workers present; Slight Odor;	very slight oil odor workers cleaning off bobcat ATRID1882
04/14/2013	08:33	UltraRAE	Benzene		<	0.05	ppm	44B	34.9638242	-92.4284833	West side of 44 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	very slight oil odor workers cleaning off bobcat batch 303024 ATRID1882
04/14/2013	08:36	MultiRAE	VOC		<	0.1	ppm	40D	34.9634268	-92.42823138	East side of 40 Starlite Rd	No Visible Oil; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor decon station set up 8n street ATRID1882
04/14/2013	08:38	MultiRAE	H2S		<	1	ppm	40D	34.9634268	-92.42823138	East side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor decon station set up in street ATRID1882
04/14/2013	08:38	UltraRAE	Benzene		<	0.05	ppm	40D	34.9634268	-92.42823138	East side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor decon station set up in street batch 303024 ATRID1882
04/14/2013	08:41	MultiRAE	VOC		<	0.1	ppm	40C	34.9634972	-92.4282334	East side of 40 Starlite Rd	Crude oil odor; Visible Oil; Residence; No work activity; Workers not present; Slight Odor;	line of oil visible along house sigh oil odor ATRID1882
04/14/2013	08:42	MultiRAE	H2S		<	1	ppm	40C	34.9634972	-92.4282334	East side of 40 Starlite Rd	Crude oil odor; Visible Oil; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor small line of visible oil along house ATRID1882
04/14/2013	08:43	UltraRAE	Benzene		<	0.05	ppm	40C	34.9634972	-92.4282334	East side of 40 Starlite Rd	Crude oil odor; Visible Oil; Residence; No work activity; Workers not present; Slight Odor;	batch 303024 line of visible oil along house skiing oil odor ATRID1882
04/14/2013	08:44	MultiRAE	VOC		<	0.1	ppm	40B	34.9635068	-92.42839371	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor ATRID1882
04/14/2013	08:46	MultiRAE	H2S		<	1	ppm	40B	34.9635068	-92.42839371	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor ATRID1882
04/14/2013	08:46	UltraRAE	Benzene		<	0.05	ppm	40B	34.9635068	-92.42839371	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Residence; No work activity; Workers not present; Slight Odor;	slight oil oder batch 303024 ATRID1882
04/14/2013	08:47	MultiRAE	VOC		<	0.1	ppm	40A	34.9635066	-92.42849401	North side of 40 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
04/14/2013	08:48	MultiRAE	H2S		<	1	ppm	40A	34.9635066	-92.42849401	North side of 40 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
04/14/2013	08:49	UltraRAE	Benzene		<	0.05	ppm	40A	34.9635066	-92.42849401	North side of 40 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; No Visible Oil; Exhaust fumes odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 303024 ATRID1882 slight exhaust odors from bobcat a few hours down ATRID1882
04/14/2013	08:50	MultiRAE	VOC		<	0.1	ppm	36A	34.9636094	-92.42814123	North side of 36 Starlite Rd	No Visible Oil; Exhaust fumes odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	ATRID1882
04/14/2013	08:53	MultiRAE	H2S		<	1	ppm	36A	34.9636094	-92.42814123	North side of 36 Starlite Rd	No Visible Oil; Exhaust fumes odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight exhaust odor from bobcat a house down ATRID1882
04/14/2013	08:53	UltraRAE	Benzene		<	0.05	ppm	36A	34.9636094	-92.42814123	North side of 36 Starlite Rd	No Visible Oil; Exhaust fumes odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor area excavated ATRID1882
04/14/2013	08:54	MultiRAE	VOC		<	0.1	ppm	36B	34.9636606	-92.42805142	North side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor ATRID1882
04/14/2013	08:57	MultiRAE	H2S		<	1	ppm	36B	34.9636606	-92.42805142	North side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor batch 303024 ATRID1882
04/14/2013	08:57	UltraRAE	Benzene		<	0.05	ppm	36B	34.9636606	-92.42805142	North side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor kind of visible oil along house ATRID1882
04/14/2013	08:59	MultiRAE	H2S		<	1	ppm	36C	34.9635199	-92.42796122	East side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor visible oil along home ATRID1882
04/14/2013	08:59	MultiRAE	VOC		<	0.1	ppm	36C	34.9635199	-92.42796122	East side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 303024 visible oil along home slight oil odor ATRID1882
04/14/2013	09:00	UltraRAE	Benzene		<	0.05	ppm	36C	34.9635199	-92.42796122	East side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	

04/14/2013	09:02	MultiRAE	VOC
04/14/2013	09:03	MultiRAE	H2S
04/14/2013	09:04	UltraRAE	Benzene
04/14/2013	09:06	MultiRAE	VOC
04/14/2013	09:07	MultiRAE	H2S
04/14/2013	09:08	UltraRAE	Benzene
04/14/2013	09:09	MultiRAE	VOC
04/14/2013	09:10	MultiRAE	H2S
04/14/2013	09:11	UltraRAE	Benzene
04/14/2013	09:12	MultiRAE	VOC
04/14/2013	09:13	MultiRAE	H2S
04/14/2013	09:14	UltraRAE	Benzene
04/14/2013	09:16	MultiRAE	VOC
04/14/2013	09:17	MultiRAE	H2S
04/14/2013	09:17	UltraRAE	Benzene
04/14/2013	09:19	MultiRAE	VOC
04/14/2013	09:20	MultiRAE	H2S
04/14/2013	09:21	UltraRAE	Benzene
04/14/2013	09:23	MultiRAE	VOC
04/14/2013	09:23	MultiRAE	H2S
04/14/2013	09:23	UltraRAE	Benzene
04/14/2013	09:29	MultiRAE	VOC
04/14/2013	09:30	MultiRAE	H2S
04/14/2013	09:31	UltraRAE	Benzene
04/14/2013	09:32	MultiRAE	VOC
04/14/2013	09:33	MultiRAE	H2S
04/14/2013	09:34	UltraRAE	Benzene
04/14/2013	09:35	MultiRAE	VOC
04/14/2013	09:36	MultiRAE	H2S
04/14/2013	09:36	UltraRAE	Benzene
04/14/2013	09:38	MultiRAE	VOC
04/14/2013	09:38	MultiRAE	H2S
04/14/2013	09:39	UltraRAE	Benzene
04/14/2013	09:40	MultiRAE	VOC
04/14/2013	09:41	MultiRAE	H2S
04/14/2013	09:41	UltraRAE	Benzene
04/14/2013	09:43	MultiRAE	VOC
04/14/2013	09:44	MultiRAE	H2S
04/14/2013	09:44	UltraRAE	Benzene
04/14/2013	09:45	MultiRAE	VOC
04/14/2013	09:46	MultiRAE	H2S

<	0.1	ppm	36D	34.9634271	-92.42798418	East side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor 2 roll offs in street ATRID1882
<	1	ppm	36D	34.9634271	-92.42798418	East side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor 2 roll offs in street ATRID1882
<	0.05	ppm	36D	34.9634271	-92.42798418	East side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; Community Center; Workers not present; Slight Odor;	slight oil odor 2 full offs in street ATRID1882
<	0.1	ppm	32D	34.9634046	-92.42774521	East side of 32 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; boom present; Area evacuated; Residence; Workers present; Slight Odor;	vac truck in street slight exhaust odor ATRID1882
<	1	ppm	32D	34.9634046	-92.42774521	East side of 32 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; boom present; Area evacuated; Residence; Workers present; Slight Odor;	slight exhaust odor ATRID1882
<	0.05	ppm	32D	34.9634046	-92.42774521	East side of 32 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; boom present; Area evacuated; Residence; Workers present; Slight Odor;	slight exhaust odor vac truck in street ATRID1882
<	0.1	ppm	32C	34.9634975	-92.42773831	East side of 32 Starlite Rd	Crude oil odor; Visible Oil; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor small line of oil visible on side of house ATRID1882
<	1	ppm	32C	34.9634975	-92.42773831	East side of 32 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor small line of oil along house ATRID1882
<	0.05	ppm	32C	34.9634975	-92.42773831	East side of 32 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 303024 slight oil odor ATRID1882
<	0.1	ppm	32B	34.9636034	-92.42773109	North side of 32 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	area excavated ATRID1882
<	1	ppm	32B	34.9636034	-92.42773109	North side of 32 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	area excavated ATRID1882
<	0.05	ppm	32B	34.9636034	-92.42773109	North side of 32 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 area excavated ATRID1882
<	0.1	ppm	32A	34.9635741	-92.42786323	North side of 32 Starlite Rd	No odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	small line of oil along back of house ATRID1882
<	1	ppm	32A	34.9635741	-92.42786323	North side of 32 Starlite Rd	No odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	small line of oil along back of house ATRID1882
<	0.05	ppm	32A	34.9635741	-92.42786323	North side of 32 Starlite Rd	No odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	small line of oil along back side of house ATRID1882
<	0.1	ppm	28A	34.9635142	-92.42748061	East side of 28 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor small line of oil along home ATRID1882
<	1	ppm	28A	34.9635142	-92.42748061	East side of 28 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor small line of oil along home ATRID1882
<	0.05	ppm	28A	34.9635142	-92.42748061	East side of 28 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 303024 small line of oil along home slight oil odor ATRID1882
<	0.1	ppm	28B	34.9633791	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; Area evacuated; Residence; Workers present; Slight Odor;	slight exhaust odor ATRID1882
<	1	ppm	28B	34.9633791	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; Area evacuated; Residence; Workers present; Slight Odor;	slight exhaust odor ATRID1882
<	0.05	ppm	28B	34.9633791	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; Area evacuated; Residence; Workers present; Slight Odor;	batch 303024 ATRID1882
<	0.1	ppm	24B	34.9633823	-92.42725689	East side of 24 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight exhaust odor from vac truck on street ATRID1882
<	1	ppm	28B	34.9633791	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight exhaust odor from vac truck on street ATRID1882
<	0.05	ppm	28B	34.9633791	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Exhaust fumes odor; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight exhaust odor from vac truck on street ATRID1882
<	0.1	ppm	24A	34.9634817	-92.42724502	East side of 24 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	trench made between homes ATRID1882
<	1	ppm	24A	34.9634817	-92.42724502	East side of 24 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	track dug between homes ATRID1882
<	0.05	ppm	24A	34.9634817	-92.42724502	East side of 24 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batchv303024 trench between homes ATRID1882
<	0.1	ppm	24C	34.9636065	-92.42720585	North side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	area had been excavated ATRID1882
<	1	ppm	24C	34.9636065	-92.42720585	North side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	area has been escuvated ATRID1882
<	0.05	ppm	24C	34.9636065	-92.42720585	North side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batcu 303024 area has been escuvated ATRID1882
<	0.1	ppm	20B	34.9635036	-92.42699492	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	20B	34.9635036	-92.42699492	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	20B	34.9635036	-92.42699492	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1882
<	0.1	ppm	20A	34.9633791	-92.42699801	East side of 20 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	vac Rick on street not running ATRID1882
<	1	ppm	20A	34.9633791	-92.42699801	East side of 20 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	vac truck parked on dtrett ATRID1882
<	0.05	ppm	20A	34.9633791	-92.42699801	East side of 20 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 vac truck parked in street ATRID1882
<	0.1	ppm	16B	34.9635051	-92.42674934	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	16B	34.9635051	-92.42674934	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	16B	34.9635051	-92.42674934	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.1	ppm	16A	34.9633847	-92.42675423	East side of 16 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	vac truck parked in street ATRID1882
<	1	ppm	16A	34.9633847	-92.42675423	East side of 16 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882

04/14/2013	10:23	MultiRAE	VOC
04/14/2013	10:23	MultiRAE	H2S
04/14/2013	10:23	UltraRAE	Benzene
04/14/2013	10:25	MultiRAE	VOC
04/14/2013	10:25	MultiRAE	H2S
04/14/2013	10:25	UltraRAE	Benzene
04/14/2013	10:27	MultiRAE	VOC
04/14/2013	10:28	MultiRAE	H2S
04/14/2013	10:29	UltraRAE	Benzene
04/14/2013	10:30	MultiRAE	VOC
04/14/2013	10:30	MultiRAE	H2S
04/14/2013	10:31	UltraRAE	Benzene
04/14/2013	10:33	MultiRAE	VOC
04/14/2013	10:34	MultiRAE	H2S
04/14/2013	10:35	UltraRAE	Benzene
04/14/2013	10:36	MultiRAE	VOC
04/14/2013	10:37	MultiRAE	H2S
04/14/2013	10:38	UltraRAE	Benzene
04/14/2013	10:39	MultiRAE	VOC
04/14/2013	10:39	MultiRAE	H2S
04/14/2013	10:41	UltraRAE	Benzene
04/14/2013	10:43	MultiRAE	VOC
04/14/2013	10:43	MultiRAE	H2S
04/14/2013	10:44	UltraRAE	Benzene
04/14/2013	10:45	MultiRAE	VOC
04/14/2013	10:46	MultiRAE	H2S
04/14/2013	10:46	UltraRAE	Benzene

<	0.1	ppm	23A	34.963075	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	23A	34.963075	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	23A	34.963075	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.1	ppm	27B	34.9629411	-92.42794491	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	27B	34.9629411	-92.42794491	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	27B	34.9629411	-92.42794491	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.1	ppm	27A	34.9630918	-92.42794563	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	hole dug in yard by road ATRID1882
<	1	ppm	27A	34.9630918	-92.42794563	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	hole dug in yard by road ATRID1882
<	0.05	ppm	27A	34.9630918	-92.42794563	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 hole dug inbyard by road ATRID1882
<	0.1	ppm	31B	34.962949	-92.42818009	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	31B	34.962949	-92.42818009	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	31B	34.962949	-92.42818009	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1882
<	0.1	ppm	31A	34.9630789	-92.42817822	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	31A	34.9630789	-92.42817822	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	31A	34.9630789	-92.42817822	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1882
<	0.1	ppm	3D	34.9630952	-92.42844217	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; Workers present;	workers plenty in street ATRID1882
<	1	ppm	3D	34.9630952	-92.42844217	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; Workers present;	workers present in street ATRID1882
<	0.05	ppm	3D	34.9630952	-92.42844217	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; Workers present;	workers present in street ATRID1882
<	0.1	ppm	3C	34.9629362	-92.42844266	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	3C	34.9629362	-92.42844266	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	3C	34.9629362	-92.42844266	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1882
<	0.1	ppm	3B	34.9631284	-92.42864003	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; Workers present;	soldiers present in street ATRID1882
<	1	ppm	3B	34.9631284	-92.42864003	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; Workers present;	workers present in street ATRID1882
<	0.05	ppm	3B	34.9631284	-92.42864003	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; Workers present;	workers present in street ATRID1882
<	0.1	ppm	3A	34.9629608	-92.42865382	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	1	ppm	3A	34.9629608	-92.42865382	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1882
<	0.05	ppm	3A	34.9629608	-92.42865382	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1882